


— Plot 22 —





Ground floor

First floor







C CupboardWC Cloakroom

A/C Airing cupboardB Boiler

F/F Fridge freezerWM Washing machine

Total Internal Area	88.55 sq m
Kitchen	2.4 x 3.6m
Living/Dining	5.0 x 5.3m
Master Bedroom	5.0 x 3.4m
Bedroom 2	5.0 x 3.3m








— Plot 23 —





Ground floor

First floor






C CupboardWC Cloakroom

A/C Airing cupboardB Boiler

F/F Fridge freezerWM Washing machine

Total Internal Area	88.55 sq m
Kitchen	2.4 x 3.6m
Living/Dining	5.0 x 5.2m
Master Bedroom	5.0 x 3.4m
Bedroom 2	5.0 x 3.3m


Very energy afficient - lower	running costs		
(92 plus) A			92
(81-91)	В		
(69-80)	C		
(55-68)	D		
(39-54)	[3	
(21-38)		F	
(1-20)		G	





— Plot 24 —





Ground floor

First floor





C CupboardWC Cloakroom


A/C Airing cupboard

Boiler

F/F Fridge freezerWM Washing machine

Total Internal Area	88.55 sq m
Kitchen	2.4 x 3.6m
Living/Dining	5.0 x 5.3m
Master Bedroom	5.0 x 3.4m
Bedroom 2	5.0 x 3.3m


Very energy afficient - lowe	running costs			
(92 plus) A				00
(81-91)	В		'	90
(69-80)	C			
(55-68)	D			
(39-54)	Ξ			
(21-38)		F		
(1-20)		G		





Plot 25 —





Ground floor

First floor






C CupboardWC Cloakroom

A/C Airing cupboardB Boiler

F/F Fridge freezerWM Washing machine

Total Internal Area	88.55 sq m
Kitchen	2.4 x 3.6m
Living/Dining	5.0 x 5.3m
Master Bedroom	5.0 x 3.4m
Bedroom 2	5.0 x 3.3m


90
90
2
G





— Plot 26 —





Ground floor

First floor






C CupboardWC Cloakroom

A/C Airing cupboardB Boiler

F/F Fridge freezerWM Washing machine

Total Internal Area	88.55 sq m
Kitchen	2.4 x 3.6m
Living/Dining	5.0 x 5.3m
Master Bedroom	5.0 x 3.4m
Bedroom 2	5.0 x 3.3m


Very energy efficient - low	er running costs		
(92 plus) A			92
(81-91)	В		
(69-80)	C		
(55-68)	D		
(39-54)	[8		
(21-38)		F	
(1-20)		G	





Plot 27 —





Ground floor

First floor






Cupboard Cloakroom A/C Airing cupboard Boiler

Fridge freezer Washing machine Loft hatch

Total Internal Area	88.55 sq m
Kitchen	2.4 x 3.6m
Living/Dining	5.0 x 5.3m
Master Bedroom	5.0 x 3.4m
Bedroom 2	5.0 x 3.3m


Very energy efficient - lowe	ar running costs			
(92 plus) A				00
(81-91)	В			90
(69-80)	C			
(55-68)	D			
(39-54)		E		
(21-38)		F		
(1-20)		G	1	





— Plot 28 —





Ground floor

First floor






C CupboardWC Cloakroom


A/C Airing cupboard

Boiler

F/F Fridge freezer **WM** Washing machine


Total Internal Area	94.63 sq m
Kitchen	2.4 x 4.2m
Living/Dining	5.7 x 5.3m
Master Bedroom	5.0 x 3.0m
Bedroom 2	5.0 x 2.8m







— Plot 29 —





Ground floor







C CupboardWC Cloakroom


A/C Airing cupboard

Boiler

F/F Fridge freezerWM Washing machine

Total Internal Area	93.23 sq m
Kitchen	2.3 x 4.2m
Living/Dining	5.0 x 5.3m
Master Bedroom	5.0 x 3.0m
Bedroom 2	5.0 x 2.8m

Very energy efficient - lower	running costs		
(92 plus) A			92
(81-91)	В		
(69-80)	C		
(55-68)	D		
(39-54)	[3	
(21-38)		F	
(1-20)		G	






Three Bedroom House

— Plot 30 —





First floor





C CupboardWC Cloakroom

A/C Airing cupboard

B Boiler

F/F Fridge freezerWM Washing machine

Total Internal Area	109.13 sq m
Kitchen	2.6 x 4.5m
Living/Dining	5.2 x 6.1m
Master Bedroom	5.2 x 3.0m
Bedroom 2	3.0 x 3.9m
Bedroom 3	2.1 x 3.9m

